

RJ45
SOUND
PROBE
+ PIEZO
duplication
wiring
Phantom
supply
Sensor
detect
A Filter
C Filter
LOG / RMS
LOG / RMS
Rectifier
ADC
ADC
ADC
DSP
Leq A
Leq C
Peak
Acoustic
Test
SOUND
PROBE
PIEZO
+
-
+
-
1 2
Piezo driver
Phoenix 6pts
Ethernet
Controller
LAN
USB
Update
GPO1
GPO2
GPO
OUT
1
2
+12V
0V
GPO1 ON
GPO2 ON
OFFSET ON
MAIN DISPLAY
SECOND DISPLAY
THIRD DISPLAY
PREDITIVE
INDICATOR
Parameters
Memory
Except
AFF19
One month
data logging
Phoenix
4pts
P.SUPPLY
12V DC /
700mA max
+12V
0V
IN
OUT